


## XIKAR IS PLEASED TO INTRODUCE THE WORLD'S FIRST FULLY ADJUSTABLE ONE-STEP PUSH BUTTON CALIBRATING HYGROMETER.



- Easy to use.
- No complicated dials.
- Includes detailed instructions on salt testing.

The XIKAR Digital Hygrometer will accurately report humidity to +/- 2% at 70% RH and temperature to 1 degree F/C.

This unit can be calibrated using the salt test method. To calibrate, fill a plastic soda cap with plain table salt. Add enough water to make the salt wet, but not so much that water stands on top of the salt. Place a zip lock bag flat on a flat surface. Place the cap inside the bag with the hygrometer. Seal the bag and wait 4 hours. Through the bag, push and hold the green button until the hygrometer resets itself to 75. Once it has reset, remove from the zip lock bag. Your hygrometer is now perfectly calibrated.

Recalibrate using the salt test method anytime. However, before each calibration, it will be necessary to remove & reinsert the battery which allows the unit to reset. This unit will read humidity in the range 30% to 90%. Should the relative humidity be outside this range, the unit will show two dashes (--). This simply means the humidity is outside the readable range. The unit is functioning normally.

**NOW SPEND YOUR TIME ENJOYING YOUR CIGARS, NOT CARING FOR THEM!**

- **Lifetime Warranty**
- **SRP \$19.99**